Thomas 2-9-101-18-18

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

renent No.:

6,657,340 B2

Issue Date:

December 2, 2003

Inventor(s):

Rikuro OBARA

Title:

MOTOR AND METHOD OF MANUFACTURING THE SAME

Docket No.:

109946

Certificate

JUL 1 5 2004

of Correction

REQUEST FOR CERTIFICATE OF CORRECTION UNDER RULE 322

Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313-1450

Sir:

It is respectfully requested that a Certificate of Correction be issued in order to correct the error specified in the attached copy of Certificate of Correction Form PTO-1050.

Fig. 4 of the drawings is incorrect. Fig. 4 of the drawings was replaced with a corrected Fig. 4 submitted with the Letter to Official Draftsperson filed on August 6, 2003. The corrected Fig. 4 was not incorporated into the above identified patent. The Certificate of Correction filed herewith includes corrected Fig. 4 attached thereto.

It is believed that the errors are on the part of the Patent and Trademark Office, and therefore no fee is due in relation to this matter in accordance with the provisions of 37 C.F.R. §1.322. However, should any fee be due, please charge the same against Deposit Account No. 15-0461 in order to ensure prompt issuance of a Certificate of Correction.

Respectfully submitted,

James A. Oliff

Registration No. 27,075

Holly N. Moore

Registration No. 50,212

JAO:HNM/kzb

Date: July 12, 2004

OLIFF & BERRIDGE, PLC P.O. Box 19928 Alexandria, Virginia 22320 Telephone: (703) 836-6400 DEPOSIT ACCOUNT USE
AUTHORIZATION
Please grant any extension
necessary for entry;
Charge any fee due to our
Deposit Account No. 15-0461